

BELZONA ELASTOMERS IDEAL FOR HIGHWAY REPAIRS

CUSTOMER

State Agency / South Texas

APPLICATION DATE

Summer of 2006

APPLICATION SITUATION

OEM expansion joint filler needed repairs to stop leaks. Manufacturer did not provide a repair system.

PROBLEM

Rubber joint sealant became torn and ripped from traffic etc. A fast durable repair was sought instead of replacement of the joint seal.

PRODUCTS

Belzona® 2311 (SR Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application carried out using modified version of Belzona Know-How System Leaflet SHM-9. Areas were cleaned and roughened up using the Belzona roughing brush. Belzona® 2911 was applied and followed by Belzona® 2311.

BELZONA FACTS

After success rebuilding concrete bridge noses with Belzona® 4111, agency turned to us for help on this problem. Without this repair, the complete joint seal would have had to be removed which would have been expensive and time consuming.

PICTURES

1. Large highway expansion joint
2. Grate over sealant removed
3. Torn rubber was cleaned, roughened up and conditioned
4. Finished repair



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

