

## BELZONA SMOOTHS OUT DAIRY RAMP

### CUSTOMER

Dairy, Telford, UK

### APPLICATION DATE

2007

### APPLICATION SITUATION

The factory has grown over a number of years with each new section at different floor levels. The area in question had a very short steep ramp between the creamery and the store area.

### PROBLEM

The slope was causing product being transferred from section to section by electric hand truck to be both unstable on the pallets and a safety hazard when travelling down the slope.

### PRODUCTS

Belzona® 4111 (Magma Quartz)

### SUBSTRATE

Ceramic Tiles

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. A sponge was used to produce a slightly rough finish for slip reduction.

### BELZONA FACTS

The Factory works non-stop and the safety issue could not wait for a shutdown. The window to work in was very short, 36 hours maximum. Client chose Belzona on grounds of technical support ensuring application completed in tight time frame. The ramp looks as good as new more than 12 months later.

### PICTURES

1. Inspection of ramp prior to work
2. Application of Conditioner prior to Belzona® 4111
3. Application of Belzona® 4111 begins
4. The finished ramp



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

