

BELZONA SHAFT REPAIR ON SUBMERSIBLE PUMP

CUSTOMER

Pump refurbishment Co, Wales, UK

APPLICATION DATE

March 2007

APPLICATION SITUATION

Bore hole pump

PROBLEM

Damage to bearing surface caused by constant motion of phosphor bronze bushing

PRODUCTS

Belzona® 1131 (Bearing Metal)

SUBSTRATE

Mild Steel

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet MPT-9.

BELZONA FACTS

Belzona® 1131 chosen for self lubricating properties and most importantly - speed of repair

PICTURES

1. Pump unit complete
2. Shaft damage/wear
3. Machining following Belzona® 1131 application
4. Completed repair



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

