

## SHAFT JOURNAL OF STONE CRUSHER REPAIRED WITH BELZONA

### CUSTOMER

Chemical industry, Bulgaria

### APPLICATION DATE

July 2002

### APPLICATION SITUATION

Main shaft of primary stone crusher

### PROBLEM

Shaft damaged by seized bearing.

### PRODUCTS

Belzona® 1321 (Ceramic S-Metal)

Belzona® 9411 (Release Agent)

### SUBSTRATE

Steel

### APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

### BELZONA FACTS

Belzona allowed vital equipment to be returned to service with minimum disruption to production.

### PICTURES

1. Preparing shaft surface
2. Forming with manufactured pipe clamp
3. View of repair with former removed



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

