

## CONVENIENT BELZONA CONVEYOR BELT REPAIR

### CUSTOMER

Power Industry, Bulgaria

### APPLICATION DATE

October 2003

### APPLICATION SITUATION

Previously vulcanized joints in coal conveyor utilizing Tip Top.

### PROBLEM

Joint failing due to moisture.

### PRODUCTS

Belzona® 2311 (SR Elastomer)

Belzona® 2911 (QD Conditioner)

### SUBSTRATE

Rubber

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-6.

### BELZONA FACTS

The Belzona repair minimizes down-time and is accomplished without specialist vulcanizing equipment. this application lasted in excess of three years and Belzona is routinely used at the facility for belt repairs.

### PICTURES

1. Original joint
2. Repair area masked off and conditioned
3. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008  
Q 09335  
ISO 14001:2004  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve