

## BELZONA REPAIR OF CONVEYOR BELT

### CUSTOMER

Power plant, Bulgaria

### APPLICATION DATE

August, 2002

### APPLICATION SITUATION

5 km conveyor belt for transporting coal to the power plant

### PROBLEM

Mechanical damage on the protector/scrapper was exposing the metal reinforcement

### PRODUCTS

Belzona® 2311 (SR Elastomer)

### SUBSTRATE

Rubber

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

### BELZONA FACTS


The customer required the repair with minimum down-time. Belzona was chosen for its effective simple and fast accomplishment without special equipment as per alternative hot vulcanization method.

### PICTURES

1. View of the conveyor belt facility
2. Conditioning with Belzona® 2911
3. Belzona® 2311 used to rebuild the damage



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>