

## BELZONA ROOF APPLICATION STILL WATERTIGHT 20 YEARS ON

### CUSTOMER

Auto manufacturer, Wentzville, MO

### APPLICATION DATE

October 1988

### APPLICATION SITUATION

Parapet wall joints on visitors center leaking. Previous attempts with silicone sealant failed quickly.

### PROBLEM

Water was leaking in, staining wallpaper, ceiling tile and carpet causing an obvious unsightly mess.

### PRODUCTS

Belzona® 3111 (Flexible Membrane)

### SUBSTRATE

Exposed aggregate concrete

### APPLICATION METHOD


Application carried out in accordance with the Belzona Know-How System Leaflet RPA-10.

### BELZONA FACTS

Labor costs of applying silicone sealant, which did not work, far exceeded the cost of the Belzona application. 20 years later, no leaks!

### PICTURES

1. Belzona® 3911 being applied
2. Belzona® 3111 application
3. Follow up picture February 2008



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

