

BELZONA FLOOR REPAIR 24 YEARS ON

CUSTOMER

Auto manufacturer, Wentzville, MO

APPLICATION DATE

Summer 1984

APPLICATION SITUATION

Floor in front of highly trafficked overhead doorway leading to production area. Work had to be carefully scheduled so as not to impede constant traffic flow.

PROBLEM

Rough area caused vehicles to lose their load, creating a safety hazard and damage to package contents. In addition, the rough ride damaged sensitive electronic equipment.

PRODUCTS

Belzona® 4111 (Magma Quartz)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with the Belzona Know-How System Leaflet FPA-1. Application was carried out in two halves so as not to disrupt constant traffic flow.

BELZONA FACTS

Safety concerns were paramount. One single piece of damaged electronics far surpassed the cost of the entire Belzona application. After 24 years, there is some slight damage, but the floor is still performing satisfactorily.

PICTURES

1. Original floor in 1984
2. Belzona® 4111 application completed
3. Belzona® 4111 in February 2008



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

