

BELZONA KEEPS CUSTOMERS ROLLING

CUSTOMER

Plant rental company, Augusta SC

APPLICATION DATE

December 2007

APPLICATION SITUATION

Tire repair

PROBLEM

After the rental was returned they saw the damage and needed a repair right away, knowing the unit was booked to go right back out.

PRODUCTS

Belzona® 2311 (SR Elastomer)

SUBSTRATE

Rubber

APPLICATION METHOD

Application was carried out using a modified Belzona Know-How System Leaflet SHM-1. The Surface was roughed with roughing brush, Conditioned then gouges in tire repaired with the Belzona® 2311.

BELZONA FACTS

Belzona Elastomer was chosen for this job because of its durability, ease of application and how quickly they could get the unit back into the field again.

PICTURES

1. Damage to the tire
2. After the roughing surface conditioned
3. Belzona® 2311 completed repair



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

