

## BELZONA KITCHEN REPAIR KEEPS THE STUDENTS GOING

### CUSTOMER

University, France

### APPLICATION DATE

June 2004

### APPLICATION SITUATION

Kitchen serving the restaurant for the University students.

### PROBLEM

The tiles were degraded around the stainless steel grate. Following a health and safety inspection, the hygiene of the kitchen was reported so urgent action needed to be taken.

### PRODUCTS

Belzona® 4111 (Magma Quartz)

### SUBSTRATE

Metal, concrete and tiles

### APPLICATION METHOD

The application was carried out following the Belzona Know-How System Leaflet FPA-1.

### BELZONA FACTS

The Belzona solution offers several advantages to the customer. The excellent adhesion onto different substrates (metal, concrete & tile). The easy to clean surface, proven to be a hygienic solution. It is also resistant to the cleaning liquids used. The Belzona® 4111 is resistant to the pedestrian & trolley traffic in this environment and after 5 years in service, the repair is still in perfect condition.

### PICTURES

1. Application situation 1 before repair
2. Application situation 2 before repair
3. Application situation 1 after repair
4. Application situation 2 after repair



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

