

## BELZONA RESCUES KOMATSU LOADER

### CUSTOMER

Heavy equipment repair shop, Canada

### APPLICATION DATE

November 2008

### APPLICATION SITUATION

Komatsu transmission casing

### PROBLEM

Loader drove over rock and cracked the casing in many areas

### PRODUCTS

Belzona 1161 (Super UW-Metal)

### SUBSTRATE

Mild Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

### BELZONA FACTS

After trying welding the cracks the oil in this casing continued to leak. That's when Belzona 1161 came to the rescue. Cost of repair \$1500 vs Komatsu dealer repair over \$20,000. Loader still running after 10 months of operation maintenance free.

### PICTURES

1. Loader
2. Cracked transmission casing
3. Preparation of casing
4. Belzona 1161 after application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

