

## BELZONA PROTECTS 98% SULFURIC ACID CONTAINMENT AREA

### CUSTOMER

Power Plant, Alabama USA

### APPLICATION DATE

December 2007

### APPLICATION SITUATION

98% Sulfuric Acid containment area in water treatment plant.

### PROBLEM

Sulfuric Acid containment area coating had failed and needed re-coating.

### PRODUCTS

Belzona® 4311 (Magma CR1)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Old coating was removed using high pressure water blasting. Belzona® 4311 was applied to both containment and tank stands.

### BELZONA FACTS

Belzona has been used for years in many of Alabama Powers plants. Customer trusted product and longevity of previous applications.

### PICTURES

1. Old coating being removed
2. Belzona® 4311 being applied
3. & 4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

