

BEARING HOUSING REPAIR WITH BELZONA

CUSTOMER

Watersupply company, Bulgaria

APPLICATION DATE

April, 2003

APPLICATION SITUATION

Centrifugal pump bearing housing

PROBLEM

Housing damage after bearing seized leading to increased clearance.

PRODUCTS

Belzona® 1111 (Super Metal)

SUBSTRATE

Cast iron

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-6.

BELZONA FACTS

Belzona solution saved both time and replacement cost allowing the equipment to be quickly returned to operation.

PICTURES

1. Preparing surface
2. Belzona® 1111 applied
3. Housing with restored dimensions after machining



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

