

## BELZONA SEALS GASOLINE STORAGE TANK

### CUSTOMER

Petrochemical plant, Ontario, Canada

### APPLICATION DATE

Summer 2008

### APPLICATION SITUATION

A large gasoline storage tank

### PROBLEM

Water was collecting on this large reinforcement seam causing extensive corrosion.

### PRODUCTS

Belzona 1161 (Super UW-Metal)

### SUBSTRATE

Steel

### APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1. The application was completed from the support equipment (crane).

### BELZONA FACTS

Belzona 1161 was used due to the difficulty in accessing and removing all condensation in the repair area. The application is in excellent condition until today without any problems.

### PICTURES

1. Large corrosion area
2. Severity of corrosion clearly evident
3. Use of crane lift to access repair area
4. Completed Application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

