

BELZONA SAVES FINE PAPER PUMP CASING

CUSTOMER

Papermill, Port Elizabeth, South Africa.

APPLICATION DATE

2009

APPLICATION SITUATION

Pump handling fine pulp.

PROBLEM

Badly corroded pump volute could not be put back in service in such bad condition

PRODUCTS

Belzona® 1321 (Ceramic S -Metal)

SUBSTRATE

Cast Iron

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-5.

BELZONA FACTS

In the past this pump casing would be scrapped and replaced at a cost of R20,000. The Belzona repair cost R4,000, thus saving the customer over R16,000 and providing additional years of protection and service.

PICTURES

1. Corroded Pump Volute before application
2. Volute coated with Belzona® 1321
3. The refurbished pump volute ready for service



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

