

BELZONA PROTECTS STERN TUBE

CUSTOMER
Oregon, USA

APPLICATION DATE
2014

APPLICATION SITUATION
Stern tube in a US Army Ship.

PROBLEM
The US Army required standard protection against erosion and corrosion when the ship is dry docked.

PRODUCTS
Belzona 5811 (Immersion Grade)

SUBSTRATE
Steel

APPLICATION METHOD
The stern tube was grit blasted and then two coats of Belzona 5811 were brushed on. The application was carried out in accordance with Belzona Know-How System Leaflet SOS-2.

BELZONA FACTS
Belzona lasts through the expected time between inspections by the US Army.

PICTURES


1. Stern of the ship
2. Inspecting the grit blast
3. First coat of black Belzona 5811
4. Second coat of gray Belzona 5811



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

