

BELZONA IMPROVES SAFETY WITH NONSKID SURFACE

CUSTOMER

Washington, USA

APPLICATION DATE

1992

APPLICATION SITUATION

Slippery steps.

PROBLEM

Ice build-up on the steps was causing slip problems. The chemical deicer was destroying the concrete.

PRODUCTS

Belzona 4411 (Granogrip)

Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Concrete

APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. The surface was blasted to remove all surface laitence. Belzona 4411 was brushed onto the surface and Belzona 9221 was spread on top.

BELZONA FACTS

The nonskid surface remained perfect until the building was demolished over 20 years later.

PICTURES

1. Blasting the concrete
2. Brushing on Belzona 4411
3. Sprinkling on Belzona 9221
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

