

BELZONA STEPS UP TO THE CHALLENGE

CUSTOMER

Waterloo, ON, Canada

APPLICATION DATE

June 2011

APPLICATION SITUATION

Stairs to a municipal recreational center.

PROBLEM

Spalled concrete around hand rail post.

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 for rebuilding worn and damaged floor surfaces. The step around the hand rail was prepared by removing any loose material. Belzona 4911 (Magma TX Conditioner) was applied using a brush and Belzona 4131 was applied directly on to the conditioned surface, initially spreading to a general level using normal screeding techniques and then using a metal straight edge.

BELZONA FACTS

Belzona 4131 is a two-component system for the repair and resurfacing of concrete and stonework. This high performance, non-porous resurfacing material provides excellent protection against the effects of abrasion, impact, vibration and chemical attack.

PICTURES

1. Prior to application
2. Preparation in process
3. Application in process
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

