

BELZONA SAVES DRAIN DAMAGED BY CHEMICALS

CUSTOMER

Washington, USA

APPLICATION DATE

1993

APPLICATION SITUATION

Damaged concrete in kitchen drain.

PROBLEM

Chemicals used to clean equipment in the kitchen were destroying the concrete in the drain.

PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 4311 (Magma CR1)

SUBSTRATE

Concrete and Steel

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The concrete was cleaned and the steel was ground. Belzona 4111 was troweled over the area. A coat of Belzona 4311 was brushed over the surface, including the steel drain, to protect from chemical attack.

BELZONA FACTS

They had been looking for a solution for several months. There were no alternatives.

PICTURES

1. Grinding the steel drain
2. Conditioning the concrete
3. Troweling in the Belzona 4111
4. A coat of Belzona 4311 brushed over the drain surface



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve