

BELZONA PROTECTS RUDDERS

CUSTOMER

BC, Canada

APPLICATION DATE

May 2003

APPLICATION SITUATION

Rudders

PROBLEM

The rudders suffer from serious cavitation problems.

PRODUCTS

Belzona 1311 (Ceramic R Metal)

Belzona 1341 (Supermetalglide)

SUBSTRATE

Mild Steel

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SOS 1,2

BELZONA FACTS

Application of Belzona 1341 Supermetalglide will help reduce the effects of cavitation between dry dockings.

PICTURES

1. Rudder after grit blasting
2. Excessively cavitated areas are rebuilt with Belzona 1311 before being over coated with Belzona 1341 Supermetalglide
3. Final coat of Belzona 1341 Supermetalglide (Grey) applied and force cured with heat lamps to meet deadline.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA[®]
Repair • Protect • Improve