

## BELZONA REBUILDS AND PROTECTS RUDDERS

### CUSTOMER

BC, Canada

### APPLICATION DATE

December 2004

### APPLICATION SITUATION

Rudder

### PROBLEM

Vessel rudders are subjected to continuous erosion and cavitation attack.

### PRODUCTS

Belzona 1311 (Ceramic R Metal) Belzona 1341 (Supermetalglide)

### SUBSTRATE

Mild steel

### APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SOS-1/2

### BELZONA FACTS

### PICTURES

1. Rudders in set up after blasting ready for application
2. Rudders after application of 2 coats of Belzona 1341 Supermetalglide
3. Condition of rudders / rudder horn after 2.5 years in service with Belzona coating.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve