

BELZONA REPAIRS AND PROTECTS BULB GENERATOR SET

CUSTOMER

Hydropower Plant - France

APPLICATION DATE

March 2001

APPLICATION SITUATION

Bulb generator set.

PROBLEM

Important infiltration and corrosion between stainless steel jacket and turbine housing.

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1341 (Supermetalglide)

SUBSTRATE

Steel and Stainless steel

APPLICATION METHOD



The damaged junction was repaired with Belzona 1111 and protected with Belzona 1341. The application was completed by the customer.

BELZONA FACTS

Quick, on-site and cold repair.

PICTURES

1. General view of the housing
2. Junction between steel and stainless steel
3. Completed repair and protection



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

