

BELZONA REPAIRS LEAKS IN WATER FEATURE

CUSTOMER

Toronto, ON, Canada

APPLICATION DATE

1987

APPLICATION SITUATION

Water feature.

PROBLEM

Leaks in the water feature.

PRODUCTS

Belzona 3111 (Flexible Membrane)

Belzona 3911 (PSC Surface Conditioner)

Belzona 3921 (GSC Surface Conditioner)

SUBSTRATE

Concrete and steel

APPLICATION METHOD


The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6 for waterproofing gutters and standing water areas. The area was cleaned of any debris and blasted to prepare the surface. Belzona 3911 was applied to the concrete and Belzona 3921 was applied to the steel using a brush. Belzona 3111 was applied to the surface using a brush as a two coat system.

BELZONA FACTS


Belzona 3111 is a single component, solvent free, microporous coating for the long-term repair and protection of all types of roofs. This versatile liquid applied material provides outstanding weatherproofing and waterproofing properties with excellent protection against infrared and ultra violet radiation and provides long-term protection for 20 years plus.

PICTURES

1. Water feature
2. Prior to application
3. Completed application
4. Water feature back in service



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

