

BELZONA PROVIDES NON-SLIP SURFACE AT SCHOOL ENTRANCE.

CUSTOMER

School, Derbyshire

APPLICATION DATE

August 2014

APPLICATION SITUATION

Worn Steps

PROBLEM

Steps presented a slip hazard to pupils, staff and visitors when entering and exiting the school.

PRODUCTS

Belzona 4411 (Granogrip)

Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Concrete

APPLICATION METHOD


The application was carried out in accordance with Belzona System Leaflet FPA-8. Belzona 9221 was encapsulated in the Belzona 4411 and applied in an even coat.

BELZONA FACTS

The school had used Belzona 4411 in the past and were pleased with the results and therefore chose Belzona again for this application. The entire application was completed in one day. The Belzona 4411 yellow provides a visual guide to the step nosings as well as a hard wearing non-slip surface.

PICTURES

1. Damaged Steps
2. Damaged steps - close up
3. Completed Application
4. Completed Application - close up



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

