

## BELZONA 4111 BETTER THAN CONCRETE

### CUSTOMER

Mass Transit Company, South Texas

### APPLICATION DATE

January 2005

### APPLICATION SITUATION

Drainage channel at entrance to bus depot. "Speed hump" also required to control traffic entering depot

### PROBLEM

Heavy buses rolling over drainage channel cracked the concrete curb. Client also wanted to compare Belzona 4111 to concrete as a repair material in side by side comparison.

### PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 4911 (Magma TX Conditioner)

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet FPA-1.

### BELZONA FACTS

After almost one year, Belzona 4111 still in tact while the concrete had not held up in this heavily trafficked bus depot. Repairs carried out quickly with minimal disruption to traffic.

### PICTURES

1. Damaged drainage channel curb
2. Area prepared and conditioned with Belzona 4911
3. Belzona 4111 layer in place
4. Completed application



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

