

## BELZONA REPAIRS NEW HEAVY EQUIPMENT TIRE

### CUSTOMER

Equipment Dealership, South Central Kansas

### APPLICATION DATE

June, 2007

### APPLICATION SITUATION

New front end loader being delivered to the local dealership.

### PROBLEM

When the transport unloaded this brand new loader, the tire was damaged.

### PRODUCTS

Belzona® 2311 (SR Elastomer)

### SUBSTRATE

Rubber

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1. The surface was prepared with a roughing brush and conditioned with Belzona® 2911 (QD Conditioner). The gouges in the rubber tire cover were rebuilt with Belzona® 2311.

### BELZONA FACTS

The Belzona repair was completed quickly and its excellent adhesion and abrasion resistance will ensure it continues to perform in service.

### PICTURES

1. Damaged portion of the tire
2. Roughened surface
3. Surface conditioned
4. Tire rebuilt with Belzona® 2311



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

