

## BELZONA LEVELS LOADING QUAY

### CUSTOMER

Animal feed manufacturer, Canada

### APPLICATION DATE

November 2006

### APPLICATION SITUATION

Loading quay

### PROBLEM

The uneven surface (measuring 1 inch) between two concrete sections was causing impact problems to forklift trucks driving through. The impact caused pain to the personnel operating these trucks, as well as jeopardising the balance and security of the loads.

### PRODUCTS

Belzona® 4111 (Magma-Quartz)

### SUBSTRATE

Concrete

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

### BELZONA FACTS

A less costly alternative repair had lasted only 6 months (picture 1). Belzona 4111 is still intact after 1 year in service, due to its excellent bond strength, impact resistance and compressive strength.

### PICTURES

1. The failed previous alternative repair
2. Surface preparation
3. Completed application
4. Application after 1 year



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

