

## BELZONA MAKES WALKWAY SAFE

### CUSTOMER

Cider producer, Herefordshire, UK

### APPLICATION DATE

September 2011

### APPLICATION SITUATION

Walkway in production area of Cider Plant

### PROBLEM

Delamination of resin floor had caused a trip hazard. When the repair was looked at they noted that there was a slip hazard in the same area.

### PRODUCTS

Belzona® 4131 (Magma Screed)

Belzona® 4411 (Granogrip)

### SUBSTRATE

Concrete

### APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona® 4131 applied to level floor area before applying Belzona® 4411 grip system.

### BELZONA FACTS

When routine maintenance was carried out they would step out of a small bund with wet feet. Belzona® 4131 ability to be feather edged allowed easy levelling of the walkway. The yellow Belzona® 4411 was chosen as both a positive grip system and as a visual aid.

### PICTURES

1. Trip hazard levelled with Belzona® 4131
2. Application of Belzona® 4411
3. Removal of masking tape
4. Completed application.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China  
[www.belzona.com](http://www.belzona.com)

