

BELZONA SEALS ROOF OVER PRODUCTION AREA

CUSTOMER

Manufacturer, UK

APPLICATION DATE

September 2012

APPLICATION SITUATION

Extraction outlets on roof over production area.

PROBLEM

The effect of weather and UV caused rubber seals around ductwork penetrations to degrade allowing rainwater to leak directly into the production area creating disruption in production and safety issues.

PRODUCTS

Belzona® 2211 (MP Hi-Build Elastomer)

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1 and 6. The joints were resealed with Belzona Elastomer, before applying a fully reinforced Belzona® 3111 Flexible Membrane system.

BELZONA FACTS

Belzona system was applied in 2 days without disrupting production, giving a long term water and weather resistant solution.

PICTURES

1. Deteriorated joint
2. Belzona® 2211 applied to seal gap
3. All joints sealed with Belzona Elastomer
4. Fully Reinforced Belzona® 3111 system applied to give additional sealing and protection



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

