

BELZONA PROTECTS FLARE DRUM

CUSTOMER

Refinery, UK

APPLICATION DATE

November 2011

APPLICATION SITUATION

Flare knock-out drum

PROBLEM

Vessel suffering internal corrosion. Coating required to extend service life of the vessel.

PRODUCTS

Belzona® 1391 (Ceramic HT)

SUBSTRATE

Carbon Steel

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

Belzona® 1391 provides excellent corrosion protection at elevated temperatures. In particular the coating is capable of withstanding the extreme variations in temperature and pressure the vessel is exposed to. The ambient temperature curing coating lends itself to application on-site.

PICTURES

1. 2 & 3. Various views of the Belzona® 1391 applied to the vessel interior.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

