

BELZONA REPAIRS CABLE REINFORCED CONVEYOR BELT

CUSTOMER
BC, Canada

APPLICATION DATE
August 1996

APPLICATION SITUATION
Cracked cable stayed belt

PROBLEM
Cable stayed belt would develop cracks over a period of time.

PRODUCTS
Belzona 2311 (SR Elastomer)



SUBSTRATE
Rubber

APPLICATION METHOD
Application carried out in accordance with Belzona Know-How System Leaflet SHM-1

BELZONA FACTS
Because of its rapid set-up time, coupled with its quick development of mechanical strength, Belzona 2311 allowed repairs to be made to the belt during unscheduled or short shut-downs.

PICTURES

1. View of preparation in progress
2. Close-up of one of the repair areas
3. Completed application.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • Thailand
www.belzona.com

