

BELZONA ELASTOMERS REPAIR CUT IN TIRE

CUSTOMER
BC, Canada

APPLICATION DATE
June 1995

APPLICATION SITUATION
Damaged tire

PROBLEM
Tire on earthmoving equipment had been badly damaged.

PRODUCTS
Belzona 2311 (SR Elastomer)
Belzona 2911 (Elastomer QD Conditioner)


SUBSTRATE
Rubber

APPLICATION METHOD
The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS
Quick repairs to this issue prevented further damage to the underlying reinforcing plies, allowing the equipment to continue operating until a scheduled downtime. Belzona 2311 cures rapidly, reaching full mechanical strength in about 2 hours.

PICTURES

1. View of equipment and the extent of the damaged area
2. Surface around the damaged area prepared and coated with Belzona 2911
3. Damaged area sealed and rebuilt with Belzona 2211



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

