

BELZONA REPAIRS AND SEALS CRACKED TRANSMISSION CASING

CUSTOMER
BC, Canada

APPLICATION DATE
N/A

APPLICATION SITUATION
Replacing cracked gear box

PROBLEM
Repairing cracked and leaking transmission housing

PRODUCTS
Belzona 1111 (Super Metal)


SUBSTRATE
Cast iron

APPLICATION METHOD
Application carried out in accordance with a modified version of Belzona Know-How System Leaflet MPT-1

BELZONA FACTS
A Belzona repair allowed casing to be repaired with the minimum amount of disassembly and downtime.

PICTURES

1. View of equipment
2. Crack "v" out and the surface area around it roughened
3. Belzona 1111 applied to the area around the repair
4. A reinforcement plate bolted over the uncured Belzona material to provide additional mechanical strength to the area.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

