

BELZONA 2311 (SR ELASTOMER) USED FOR EMERGENCY REPAIRS

CUSTOMER
BC, Canada

APPLICATION DATE
2000

APPLICATION SITUATION
Belt repair in gravel pit

PROBLEM
A small cut had developed in a section of the belt

PRODUCTS
Belzona 2311 (SR Elastomer)

SUBSTRATE
Rubber

APPLICATION METHOD
Application carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1

BELZONA FACTS
The use of Belzona 2311 allowed the yard to repair the damage before it became more serious. The quick setting properties of the repair material also allowed the repair to be completed during a lunch break ensuring no downtime.

PICTURES

1. View of the cut in the belt
2. Initial preparation underway
3. The loose piece of belting has been cut away and area around it roughed up with a special roughing tool
4. Repair in progress



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

