

## BELZONA 2200 SERIES ELASTOMERS REPAIR SPLIT CONVEYOR BELT

### CUSTOMER

BC, Canada

### APPLICATION DATE

June 2000

### APPLICATION SITUATION

Split belt repair

### PROBLEM

A mechanical breakdown had caused the belt to be split over a length of approximately 100 feet.

### PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

Belzona 2911 (QD Conditioner)

### SUBSTRATE

Rubber

### APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1

### BELZONA FACTS

The use of the two Belzona products allowed the plant to repair the damage in-situ, saving many hours of downtime.

### PICTURES

1. Conveyor system in need of repair
2. The damaged portions of the belt were held together using mechanical fasteners
3. Close-up of fasteners and the prepared belt surfaces conditioned with Belzona 2911
4. The completed repair



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

