

BELZONA REPAIRS A DOCK HOSE BEFORE INSPECTION

CUSTOMER

Terminal Dock, Louisiana, USA

APPLICATION DATE

July 2013

APPLICATION SITUATION

Rubber Dock Hose with cuts.

PROBLEM

Over the years as the dock hose had been drug around the deck and over shipside, the hose had been cut and gouged.

PRODUCTS

Belzona 2311 (SR Elastomer)

Belzona 2911 (Conditioner)

SUBSTRATE

Rubber

APPLICATION METHOD


After proper surface preparation, the application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Customer spent less than \$50.00 to repair cosmetic cut in hose for Coast Guard approval to keep using the hose versus spending \$2,500 or more for a new hose.

PICTURES

1. Area being prepared for repair.
2. Area after Belzona 2911 applied.
3. Belzona 2311 applied.
4. Finished repair before tape removed.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

