

## BELZONA REPAIRS A CONVEYOR BELT

### CUSTOMER

South Louisiana, USA

### APPLICATION DATE

September 2013

### APPLICATION SITUATION

Conveyor belt with a piece missing.

### PROBLEM

Conveyor belt had a 2" x 2" piece of rubber missing.

### PRODUCTS

Belzona 2311 (SR Elastomer)

Belzona 2911 (Conditioner)

### SUBSTRATE

Rubber

### APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1. The hole in the belt was filled with Belzona 2311.

### BELZONA FACTS

Customer had made larger repairs with excellent results so it was only natural to repair this hole also. Belzona 2311 enabled the repair to be carried out with minimal downtime.

### PICTURES

1. The area prepared for repair
2. Application is complete



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

