

BELZONA REPAIRS RUBBER PRESS ROLL

CUSTOMER

Northeastern USA

APPLICATION DATE

June 2015

APPLICATION SITUATION

Rubber press roll used to laminate gasket sheets together.

PROBLEM

Rubber press roll had a hole caused by a tool impact, which made the roll unusable and not being able to create a smooth gasket.

PRODUCTS

Belzona 2311 (SR Elastomer)

Belzona 2911 (Elastomer QD Conditioner)

SUBSTRATE

Rubber & steel

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-9. The surface preparation and the application was carried out with the use of hand tools.

BELZONA FACTS

The cost of the Belzona materials used for the application was less than \$100. Replacement of the roll would have cost the asset owners thousands of dollars.

PICTURES

1. Rubber press roll
2. Deep hole in press roll
3. Cleaned, prepped and masked off hole to be repaired
4. Repaired hole and used a razor blade to cut and smooth final surface



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

