

BELZONA REPAIRED CAR PARK JOINT STILL INTACT

CUSTOMER

Shopping Centre, Brisbane, Australia

APPLICATION DATE

June 2013

APPLICATION SITUATION

The floor joint between concrete slabs in a car park.

PROBLEM

The edge nosings of the concrete slabs had been broken down to rubble after years of daily traffic making them unsightly and dangerous

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet FPA-1. The old damaged concrete was removed and cut back to a sound substrate. The area was then prepared and rebuilt with the Belzona 4111 system to restore the original profile.

BELZONA FACTS

Belzona 4111 was used for its high strength, fast curing and ease of application. The floor repair is still in good condition more than 3 years later.

PICTURES

1. The damaged floor joint
2. Conditioned and ready for repair
3. Repairs in progress
4. Repaired joint 3 years after completion



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



ISO 9001:2008
Q 09335
ISO 14001:2004
EMS 509612

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

UK • USA • Canada • China
www.belzona.com


BELZONA
Repair • Protect • Improve