

BELZONA KEEPS THE COVER ON ANNEALING OVEN

CUSTOMER

Metallurgy Company, Slovakia

APPLICATION DATE

2011

APPLICATION SITUATION

Large annealing oven at a metal manufacturing plant.

PROBLEM

The cover had distorted and did not sit correctly on the base and caused a CO₂ leakage.

PRODUCTS

Belzona 1121 (Super XL-Metal)

SUBSTRATE

Iron

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC - 7.

BELZONA FACTS

Using the Belzona solution allowed the original equipment to be used as a former, ensuring a perfect fit. Rebuilding in this way also meant the line was back up sooner than expected.

PICTURES

1. Annealing ovens.
2. Surface preparation.
3. Belzona 1121 application.
4. Cover replaced.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

