

BELZONA PREVENTS WATER PENETRATION INTO A DATA STORAGE FACILITY

CUSTOMER
Virginia, USA

APPLICATION DATE
July 2004

APPLICATION SITUATION
Steps at the entrance to a financial building.

PROBLEM
Spider cracks compromising the integrity of the staircase and allowing water to penetrate into the building's data center underground.


PRODUCTS
Belzona 4111 (Magma-Quartz)

SUBSTRATE
Concrete

APPLICATION METHOD
The entire repair was complete on a Saturday afternoon after employees vacated the building. The cracks were filled with Belzona 4111 and the entire surface was restored for waterproofing and a long-lasting protection.

BELZONA FACTS
As an alternative, the Customer considered replacing the steps, or use other coatings. Belzona was chosen as it offered minimal downtime, durability and experience with similar situations.

- PICTURES**
1. Showing Damage
 2. After powerwashing
 3. Completed application; the cracks filled, and the steps re-surfaced with Belzona 4111 for a long-term protection



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

