

BELZONA SUPERWRAP REPAIRS CRUDE OIL PIPELINE

CUSTOMER

Australia

APPLICATION DATE

November 2016

APPLICATION SITUATION

The crude oil pipeline is a critical part of the refinery and could not be shut down.

PROBLEM

Corrosion Under Insulation had created corrosion scabs to form at the underside of the pipe. Blasting of these scabs was not allowed.

PRODUCTS

Pre-fabricated plates were bonded over the scabs and then blasting could be allowed. Belzona SuperWrap II was applied over the defect areas so stop further corrosion and to keep the pipeline in service for 10 years.

SUBSTRATE

Carbon Steel

APPLICATION METHOD

Belzona SuperWrap was applied as per a specific Belzona SuperWrap method statement and design.

BELZONA FACTS

Belzona SuperWrap was chosen due to having on-site personnel to be able to design, install and supervise the application. The pipeline had to be repaired or the Customer would have had to have an unexpected shutdown.

PICTURES.

1. Corrosion scab on underside of pipe.
2. Blasting of the pipeline.
3. Application of SuperWrap II.
4. Finished application.



1.



2.



3.



4.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

