

BELZONA REPAIRS A CAR ENGINE CASING

CUSTOMER

Civil Society, Slovakia

APPLICATION DATE

2016

APPLICATION SITUATION

Cracked Engine Casing on a government vehicle.

PROBLEM

The freezing winter temperatures had caused excessive movement and a crack in the engine casing.

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Iron

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC - 1.

BELZONA FACTS

Welding this kind of damage would take a lot of time and money. Rebuilding with Belzona 1111 was a faster and more economical solution for the customer.

PICTURES

1. Cracked engine.
2. Crack detection.
3. Surface preparation.
4. Belzona 1111 application with reinforcement tape.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com


BELZONA
Repair • Protect • Improve