

## BELZONA REPAIRS TANK LEG SUPPORTS AT A DISTILLERY

### CUSTOMER

United Kingdom

### APPLICATION DATE

2018

### APPLICATION SITUATION

VAT tank leg supports at a distillery.

### PROBLEM

Several VAT tank leg supports were corroded due to the break down of the original paint system. Some tanks had already been condemned due to metal loss and through wall defects in the tank supports.

### PRODUCTS

Belzona 5811 (Immersion Grade)

### SUBSTRATE

Steel

### APPLICATION METHOD

The previous paint was removed by saturation blasting to keep the dust levels down on-site. The VAT legs were then coated by hand with Belzona 5811 in accordance with a modified version of Belzona Know-How System Leaflet TCC-5.

### BELZONA FACTS

This system provides a long-term corrosion resistance and an aesthetically pleasing finish.

### PICTURES

1. Damaged tank leg supports.
2. Damaged tank leg supports.
3. 1st coat of Belzona 5811.
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

