

## LARGE STORAGE TANK PROTECTED WITH BELZONA

### CUSTOMER

Petrochemical company, Slovakia

### APPLICATION DATE

2015

### APPLICATION SITUATION

Crude oil storage tank

### PROBLEM

The tank had been in service for twenty years and was suffering extensive corrosion damage

### PRODUCTS

Belzona 5811 (Immersion Grade)

Belzona 1111 (Super Metal)

### SUBSTRATE

Steel

### APPLICATION METHOD


Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3 & TCC-5

### BELZONA FACTS

Customer needed quick and quality repair. All protection was realized with Belzona 5811. Deep corrosion was rebuilt with Belzona 1111.

### PICTURES

1. Tank after 20 years.
2. Blasting of the basin
3. Visible damages after blasting
4. Belzona 5811 coating applied in 2 layers



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

