

BELZONA REFURBISHES BRAKE TEST ROLLERS

CUSTOMER

Vehicle testing station, Slovakia

APPLICATION DATE

2016

APPLICATION SITUATION

Brake test rollers at vehicle testing station.

PROBLEM

After many thousand tests the surface of the rollers required a new non-slip surface applying.

PRODUCTS

Belzona 1821 (Fluid Metal)

SUBSTRATE

Steel

APPLICATION METHOD

Application was carried out in accordance with modified Belzona Know-How System Leaflet SHM-12.

BELZONA FACTS

Customer needed quick repair in good quality and Belzona grip system has a proven track record for this application.

PICTURES

1. Damaged rollers
2. Belzona 9211 Supergrip Aggregate application into Belzona 1821
3. Ready to work



1.



2.



3.

For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

