

BELZONA REPAIRS JOINTS IN CONCRETE

CUSTOMER

Furniture production plant, Slovakia,

APPLICATION DATE

2015

APPLICATION SITUATION

Dilatation (contraction) joints in concrete floor.

PROBLEM

Heavy fork lift truck traffic destroyed joint nosings.

PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Concrete

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet FPA-5 and FPA-6.

BELZONA FACTS

Customer tried to repair damaged joints several times with another product but after 2 weeks problem returned. After Belzona repair customer has no problem.

PICTURES

1. Damaged dilatation joint
2. Repair in progress
3. Belzona 2211 application
4. Joints ready for work



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

