

## 4311 COATS A SULFURIC ACID TANK AT A CHEMICAL PLANT

### CUSTOMER

Northern Florida

### APPLICATION DATE

October 2017

### APPLICATION SITUATION

The Customer wanted to coat a previously uncoated Sulfuric Acid tank.

### PROBLEM

Chemical attach onto the metal was taking a toll. The area was hard to shut down due to the need for this product during production.

### PRODUCTS

Belzona 4311 (Magma CR1)

### SUBSTRATE

Carbon steel.

### APPLICATION METHOD

The contractor used a heated plural component pump to do the application as per Belzona's spray instructions. The application was done in accordance to Belzona system leaflet TCC-5.

### BELZONA FACTS

The Engineer had used Belzona at another plant and wanted to use Belzona for this application.

### PICTURES

1. The tank after blasting with Black Beauty to get the required Belzona cleanliness standard.
2. A heated plural component pump the Customer used.
3. The spray team about to start.
4. Finished application of Belzona 4311.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand  
[www.belzona.com](http://www.belzona.com)

