

BELZONA REBUILDS DAMAGED DECK FLOOR

CUSTOMER

Egypt

APPLICATION DATE

2007

APPLICATION SITUATION

Corrosion occurring on deck floor

PROBLEM

Severe pitting corrosion had occurred on the deck floor which needed rebuilding.

PRODUCTS

Belzona 1121 (Super XL-Metal)

SUBSTRATE

Mild Steel

APPLICATION METHOD


This was carried out using a modified version of Belzona Know-How System Leaflet FPA-1. After surface preparation the Belzona 1121 was applied to restore the deck to its original dimensions.

BELZONA FACTS

Belzona can return badly corroded areas back to their original dimensions and its has the capability to handle high compressive loads.

PICTURES

1. Damaged Area
2. Surface Preparation
3. Belzona 1121 application
4. Completed application



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

