

BELZONA CHOCKING REPAIR ON GEAR MOUNTING

CUSTOMER

Szarbków, Poland

APPLICATION DATE

2019

APPLICATION SITUATION

Re-levelling a steel foundation slab of a mill gear and the foundation of the mill on the plate.

PROBLEM

Gear mounting not working at full efficiency due to misalignment. Repair work need to concrete area prior to chocking.

PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 7111

SUBSTRATE

Concrete

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet GSS-2. Placing of the steel foundation slab using the Belzona 4111 and chocking the foundation of the mill plate using Belzona 7111.

BELZONA FACTS

Belzona was selected for chocking project over alternative products due to the competence and back up support of the local distributor.

PICTURES

1. Gear Equipment Picture
2. Application of Belzona 4111
3. Application of Belzona 7111
4. Chocking application complete.



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • Thailand
www.belzona.com

